From: Sent: Subject:	"Sharon Budney" [BudneySL@cdm.com]; tephanie Vaughn/R2/USEPA/US@EPA[] "Doug Simmons" [doug.simmons@aecom.com]; Willard Potter" naximis.com] "Robert Law" Wed 9/12/2012 1:35:40 PM 2012 Bathymetry Survey - Daily Status Report for September 11, 2012 Coverage.kmz
Daily Status	Report for Tuesday, September 11, 2012
Work Comp	oleted Today:
survey patc Street bridg CO4 was ne	September 11, 2012 GBA continued multi beam survey operations and performed the midhand performance tests. Survey operations today included the area between the Bridge ge and Clay Street bridge (RM 5.4 to RM 5.6), where section C03 was completed and section arly completed, and upriver of the Bellville bridge (RM 8.5 to RM 9.35), where sections D05 7 were completed. The remaining work in section C04 is along the shoreline at a higher water
States Army	rvey patch and performance tests were performed today. All results were well within United y Corps of Engineers Hydrographic Survey Manual speculations. Screen shots of the tests were OM for review.
The attache	ed coverage plot (KMZ) file shows the extent of the survey performed today.
Work Plann	ed for Tomorrow:
Multi Beam	Survey
Work plann	ed for tomorrow includes continuing the survey upriver of the Belleville Bridge.
Single Bean	n Survey

The work planned for tomorrow includes mobilizing the survey skiff to New Jersey and preparing for survey operations.
Deviations from the QAPP:
None noted.
Health and Safety Issues:
None noted.
None noted.

Robert Law, Ph.D. de maximis, inc. rlaw@demaximis.com Voice: 908-735-9315

Fax: 908-735-2132